


CINTROPUR[®] NW 50


SLEEVES 5, 10, 25, 50 & 100 µm

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
 PRESSURE DROP - PERDIDA DE CARGA


SLEEVE 5 µm




SLEEVE 10 µm



SLEEVE 25 µm



SLEEVE 50 µm



SLEEVE 100 µm

