


# CINTROPUR<sup>®</sup> NW 62


## SLEEVES 5, 10, 25, 50 & 100 µm

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST  
PRESSURE DROP - PERDIDA DE CARGA


SLEEVE 5 µm




SLEEVE 10 µm



SLEEVE 25 µm



SLEEVE 50 µm



SLEEVE 100 µm

